

TORCTOOL

TOOL MODEL: TTZ-2 W 41MM HEX LINK SN T2EA1238-096

PRESSURE/TORQUE CONVERSION CHART

Standard Torque Chart

PRESSURE IN PSI	TORQUE IN			PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	247	34	334	104
1600	263	36	357	110
1800	297	41	402	124
2000	330	46	447	138
2200	365	50	495	152
2400	400	55	542	165
2600	435	60	589	179
2800	470	65	637	193
3000	505	70	684	207
3200	539	75	731	220
3400	574	79	778	234
3600	608	84	825	248
3800	643	89	871	262
4000	677	94	918	276
4200	713	99	967	290
4400	749	104	1015	303
4600	785	109	1064	317
4800	820	113	1112	331
5000	856	118	1160	345
5200	892	123	1209	358
5400	928	128	1258	372
5600	964	133	1307	386
5800	1000	138	1356	400
6000	1036	143	1404	414
6200	1070	148	1451	427
6400	1105	153	1497	441
6600	1139	157	1544	455
6800	1173	162	1590	468
7000	1207	167	1637	482
7200	1243	172	1684	496
7400	1278	177	1732	510
7600	1313	182	1780	524
7800	1348	186	1828	538
8000	1383	191	1875	552
8200	1419	196	1924	565
8400	1455	201	1973	579
8600	1491	206	2022	593
8800	1527	211	2070	607
9000	1563	216	2119	620
9200	1599	221	2168	634
9400	1635	226	2216	648
9600	1670	231	2264	662
9800	1706	236	2312	676
10000	1741	241	2361	690